

ABSTRACT

A method for measuring a multimode optical fiber comprises: monitoring a temperature change within a measurement time in a DMD measurement of the multimode optical fiber, wherein the DMD measurement is carried out in an environment in which a magnitude of temperature change is controlled.